

GET THIS
LOOK



GET THIS LOOK

SKILL LEVEL:
INTERMEDIATE



Equipment



- Vinyl Cutter
- Heat Press

Garment



J. America — Odyssey Striped Performance Fleece Hooded Pullover Sweatshirt (#8661)

Materials



- CAD-CUT® Fashion-FILM® Metallic Silver
- CAD-CUT® Fashion-FILM® Electric Gold Prism
- CAD-CUT® Fashion-FILM® Jet Blue Stream

Accessories



- 11" x 15" Hotronix® Quick Change Platen
- Cover Sheet

How-To Instructions



Temperature: 320 degrees

Pressure: Various, noted

1. Load garment on 11" x 15" platen (landscape)
2. Preheat garment to release moisture & wrinkles
3. Place Metallic Silver Fashion-FILM, tack for 3 to 5 seconds with a cover sheet
4. Peel hot
5. Place Jet Stream Blue Fashion-FILM Electric, tack for 3 to 5 seconds with a cover sheet
6. Peel hot
7. Place Gold Prism Fashion-FILM Electric, apply for full application: 320 degrees for 15–20 seconds with a cover sheet
8. Peel hot